

## 3000V/30120V & 4000V/40120V APL/DPL WINCH MOUNTING UPDATE

Slide the winch (**REF. # 3**) onto the longer upright tube of the winch side member. Mount the winch using 3/8" x 4" bolts, washers and nuts (**REF. # 37, 16 & 19**). These should be loose at this time. Align the top hole in the winch and the upright tube so the bolt slides in and out easily. Tighten bolts in mounting bracket, then tighten the bolt in the upright tube with 3/8" fender washer, washer and nut (**REF. # 15, 16 and 19**).

