

C54 DOCK LEVELER

Thank you for purchasing our product!
Please read these instructions and follow them step by step.

STEP 1. Slide the dock level onto the leg tube of the dock.. On post dock models, secure the dock leveler in place with a ½” x 1” set screw.

STEP 2. Attach the S - hook on the cable to the dock as shown. Loosen set screws before adjusting dock.. After adjusting dock, re-tighten set screws.

CAUTION:

NEVER RELEASE WINCH HANDLE WHEN RACHET LEVER IS IN UNLOCKED POSITION WITH LOAD ON WINCH.

C54 DOCK LEVELER PARTS LIST

<u>REF. #</u>	<u>PART #</u>	<u>DESCRIPTION</u>	<u>QTY</u>
1	3008	Winch handle DL	1
2	3009	Winch DL900 W/Hdwe	1
3	3057	Cable 3/16” x 8’ W/S Hook	1
4	5056	Nut 3/8”	2
5	5084	Bolt 3/8” x 3” Gr 2	2
6	5174	Set Screw ½” x 1” (square head)	1
7	C48	Leveler Mounting Assembly	1